

Cleanup Site Details

Cleanup Site ID: 5510

Cleanup Site ID: 5510 Facility/Site ID: 9997635 UST ID: 1801 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Orondo Elementary School [Glossary](#)

Alternate Names: ORONDO ELEMENTARY SCHOOL, Orondo Elementary School LUST

LOCATION

Address: 100 ORONDO SCHOOL RD City: ORONDO Zip Code: 98843 County: Douglas
Latitude: 47.64104 Longitude: -120.21681 WRIA: 44 Legislative District: 12 Congressional District: 4 TRS: 25N 21E 28

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 10/3/2008 Current VCP? No Past VCP? No
Site Rank: 4 - Low-Moderate Risk NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Dunbar, Mark Responsible Unit: Central Active Institutional Control? Yes

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|--------------------------|-----------|----------------------------|-----------|----------------|---------------------------------|
| Orondo Elementary School | Upland | No Further Action Required | CE | Central Region | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|------------------------|-------------------|--|----------|------------------|------------------|-----------------------------|
| Environmental Covenant | Soil | Restrict Access, Prohibit Soil Disturbance | 7/2/2008 | 3125344 | Douglas | 75702000000; 75701900001 |

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|-------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Arsenic | RA | | | | | |
| Lead | RA | | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|------------------------------|
| Site Discovery/Release Report Received | Completed | | 8/25/1998 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 9/14/2005 |
| Early Notice Letter(s) | Completed | | 9/23/2005 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 12/22/2005 | 2/2/2007 |
| Hazardous Sites Listing/NPL | Completed | | 2/2/2007 |
| Interim Action | Completed | 3/29/2007 | 9/30/2007 |
| Remove site from Hazardous Sites List | Completed | | 10/3/2008 |
| Site Status Changed to NFA | Completed | | 10/3/2008 |

Cleanup Site Details

Cleanup Site ID: 5510

| SITE ACTIVITIES | | | |
|-----------------|-----------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Periodic Review | Completed | 5/21/2013 | 7/29/2013 |
| Periodic Review | Completed | 2/21/2018 | 5/21/2018 |
| Periodic Review | Planned | 4/1/2023 | 7/31/2023 |