

# Cleanup Site Details

Cleanup Site ID: 6822

Cleanup Site ID: 6822      Facility/Site ID: 89172959      UST ID: 97251      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Dodge of Bellevue      [Glossary](#)

Alternate Names: Dodge of Bellevue, Performance Dodge

## LOCATION

Address: 316 116TH AVE NE      City: BELLEVUE      Zip Code: 98004      County: King  
Latitude: 47.61339      Longitude: -122.18469      WRIA: 8      Legislative District: 41      Congressional District: 9      TRS: 25N 5E 33

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 8/8/2018      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Maurer, Christopher      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Performance Dodge	Upland	No Further Action Required	NW	Maurer, Christopher	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	RB					
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				
Polychlorinated biPhenyls (PCB)	RB					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/31/1989
LUST - Notification	Completed		4/1/1989
Site Discovery/Release Report Received	Completed		4/1/1989
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004

# Cleanup Site Details

Cleanup Site ID: 6822

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
VCP Opinion on Cleanup Action	Completed	9/20/2004	11/15/2004
Site Status Changed to NFA	Completed		11/15/2004
LUST - Site Characterization Report	Completed		9/19/2016
Reopen Site	Completed		9/19/2016
VCP Opinion on Site Cleanup	Completed	9/19/2016	8/8/2018
VCP Receipt of Plan or Report	Completed		5/24/2017
Site Status Changed to NFA	Completed		8/8/2018