

Cleanup Site Details

Cleanup Site ID: 6914

Cleanup Site ID: 6914 Facility/Site ID: 94658144 UST ID: 766 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Brumfield Twidwell [Glossary](#)

Alternate Names: BRUMFIELD TWIDWELL, BRUMFIELD TWIDWELL INC, BRUMFIELD-TWIDWELL INC, MONTESANO FORD MERCURY INC

LOCATION

Address: 301 E PIONEER AVE City: MONTESANO Zip Code: 98563 County: Grays Harbor
Latitude: 46.97943 Longitude: -123.59777 WRIA: 22 Legislative District: 19 Congressional District: 6 TRS: 17N 7W 7

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 3/10/2014 Current VCP? No Past VCP? No
Site Rank: 2 - Moderate-High Risk NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Coleman, Marv Responsible Unit: Southwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BRUMFIELD-TWIDWELL (KOLB PROPERTY)	Upland	No Further Action Required	SW	Southwest Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	6/16/2006	2006-06160114	Grays Harbor	079000400100, 075300400100, 075300400801

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RA	RA				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/14/2000
LUST - Report Received	Completed		5/5/2000
LUST - Site Characterization Report	Completed		5/5/2000
LUST - Report Received	Completed		5/8/2000
Interim Action	Completed	1/12/2005	12/31/2006
Initial Investigation / Federal Preliminary Assessment	Completed		8/1/2005
Early Notice Letter(s)	Completed		9/12/2005
Site Hazard Assessment/Federal Site Inspection	Completed	9/26/2005	11/10/2005

Cleanup Site Details

Cleanup Site ID: 6914

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		11/10/2005
Remedial Investigation and/or Feasibility Study	Completed	3/17/2006	10/1/2011
Cleanup Action Plan	Completed	11/1/2011	9/1/2013
Order/Decree/Amendment	Completed		11/15/2013
Site Status Changed to NFA	Completed		3/10/2014
Remove site from Hazardous Sites List	Completed		3/10/2014
Periodic Review	Completed	8/1/2020	12/20/2020
Periodic Review	Planned	8/1/2025	12/20/2025