

# Cleanup Site Details

Cleanup Site ID: 7520

Cleanup Site ID: 7520      Facility/Site ID: 3112128      UST ID: 5272      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: ARCO 5377      [Glossary](#)

Alternate Names: AM PM, ARCO 05377, Arco 5377, ARCO 5377 PSI 5507, ARCO 5377 PSI 5507, Arco 7025

## LOCATION

Address: 13131 BOTHELL EVERETT HWY      City: EVERETT      Zip Code: 98208      County: Snohomish  
Latitude: 47.87864      Longitude: -122.20626      WRIA: 8      Legislative District: 44      Congressional District: 1      TRS: 28N 5E 29

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: PLIA      Responsible Unit: Pollution Liability Ins Agcy      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ARCO STATION 5377	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead	C	C				
Methyl tertiary-butyl ether	C	C				
Non-Halogenated Solvents	C	C				
Petroleum-Gasoline	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		2/14/2003
LUST - Report Received	Completed		7/3/2003
LUST - Report Received	Completed		10/5/2004
LUST - Report Received	Completed		1/10/2005
LUST - Report Received	Completed		1/21/2005
LUST - Report Received	Completed		8/31/2005

# Cleanup Site Details

Cleanup Site ID: 7520

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/27/2006
LUST - Report Received	Completed		8/24/2006
LUST - Report Received	Completed		3/19/2007
LUST - Report Received	Completed		10/30/2007
LUST - Report Received	Completed		6/11/2009
LUST - Report Received	Completed		2/22/2010
LUST - Report Received	Completed		12/13/2010
LUST - Report Received	Completed		3/18/2011
LUST - Report Received	Completed		5/2/2011
Non-LUST Ind Report Received	Completed		5/26/2011
Non-LUST Ind Report Received	Completed		5/26/2011
LUST - Report Received	Completed		5/26/2011
LUST - Report Received	Completed		5/26/2011
LUST - Report Received	Completed		7/5/2012
VCP Receipt of Plan or Report	Completed		7/6/2012
LUST - Report Received	Completed		4/1/2013
LUST - Report Received	Completed		6/23/2015
LUST - Report Received	Completed		6/23/2015
LUST - Report Received	Completed		4/26/2016
LUST - Report Received	Completed		5/17/2016
LUST - Report Received	Completed		10/25/2016
LUST - Report Received	Completed		3/27/2017
LUST - Report Received	Completed		4/2/2018
VCP Status Request	Completed	8/24/2018	11/9/2018