

Cleanup Site Details

Cleanup Site ID: 88

Cleanup Site ID: 88 Facility/Site ID: 762 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: L-Bar Site [Glossary](#)

Alternate Names: L BAR PRODUCTS, L BAR PRODUCTS INC, L Bar Site Northwest Alloys, L-Bar Site, Phoenix Resource Recovery

LOCATION

Address: HWY 395 City: CHEWELAH Zip Code: 99109 County: Stevens
Latitude: 48.25562 Longitude: -117.71547 WRIA: 59 Legislative District: 7 Congressional District: 5 TRS: 32N 40E 23

DETAIL

Status: Construction Complete-Performance Monitoring NFA Received? No Is PSI site? No
Statute: WPCA - Ch. 90.48 RCW NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 4 - Low-Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Loftenius, Christer Responsible Unit: Eastern Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
L-Bar Site	Upland	Construction Complete-Performance Monitoring	EA	Loftenius, Christer	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict Domestic Ground Water Extraction/Well Installation, Prevent the Reuse or Relocation of Site Soil	4/27/2001	2001 003757	Stevens	2600950; 2600500; 2600700; 2601050; 2600800; 2600000

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C	C	C			
Metals Priority Pollutants	S	S	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	9/2/1993	1/20/1994
Emergency Action	Completed	10/4/1993	12/7/1993
Hazardous Sites Listing/NPL	Completed		3/8/1994
Emergency Action	Completed	3/17/1994	7/31/1995
Order/Decree/Amendment	Completed	4/21/1994	9/20/1999
Remedial Investigation and/or Feasibility Study	Completed	1/5/1995	5/31/1999

Cleanup Site Details

Cleanup Site ID: 88

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	1/5/1995	12/31/1997
Cleanup Action Plan	Completed	5/31/1999	6/12/2000
Order/Decree/Amendment	In Process	1/24/2000	
Cleanup Action - Engineering Design	Completed	6/12/2000	3/14/2001
Cleanup - Construction	Completed	6/12/2000	10/30/2004
O & M	In Process	4/2/2001	
Cleanup - Performance Monitoring	In Process	1/10/2005	
Periodic Review	Completed	3/1/2012	4/25/2012
Periodic Review	Completed	7/9/2018	9/30/2019
Periodic Review	Planned	9/30/2024	