Cleanup Site Details

Cleanup Site ID: 8836

Cleanup Site ID: 8836 **Facility/Site ID:** 35363194 **UST ID:** 5060 Site Page | Site Documents | View Map

Cleanup Site Name: Chevron 90619 Glossary

Alternate Names: CHEVRON 90619, Chevron USA Inc SS 90619

LOCATION

Address: 1205 WASHINGTON ST **City:** BELLINGHAM **Zip Code:** 98225 **County:** Whatcom

Latitude: 48.76042 **Longitude:** -122.48815 **WRIA:** 1 **Legislative District:** 42 **Congressional District:** 2 **TRS:** 38N 2E 25

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** Yes

Statute: MTCA **NFA Date:** 1/7/2021 **Current VCP?** No **Past VCP?** No

Site Rank: 4 - Low-Moderate Risk **NFA Reason:** Ecology Supervised/Conducted Cleanup **Brownfield?** No

Site Manager: Guenther, John **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 90619	Upland	No Further Action Required	NW	Guenther, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Benzene	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/23/1991
LUST - Notification	Completed		1/25/1991
LUST - Report Received	Completed		3/11/1991
LUST - Report Received	Completed		5/21/1991
LUST - Report Received	Completed		8/26/1991
LUST - Report Received	Completed		10/11/1991
LUST - Report Received	Completed		2/27/1992
LUST - Report Received	Completed		3/23/1992
LUST - Report Received	Completed		9/22/1992

Cleanup Site Details

Cleanup Site ID: 8836

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/10/1993
LUST - Report Received	Completed		1/21/1994
LUST - Report Received	Completed		4/22/1994
LUST - Report Received	Completed		8/3/1994
LUST - Report Received	Completed		11/14/1994
LUST - Report Received	Completed		1/10/1995
LUST - Report Received	Completed		8/16/1995
LUST - Report Received	Completed		10/26/1995
LUST - Report Received	Completed		4/3/1996
Early Notice Letter(s)	Completed		8/6/2015
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	12/26/2017
Order/Decree/Amendment	Completed	8/23/2017	1/7/2021
Hazardous Sites Listing/NPL	Completed		2/7/2018
Remove site from Hazardous Sites List	Completed		1/4/2021
Site Status Changed to NFA	Completed		1/7/2021