Cleanup Site Details Cleanup Site ID: 9611									
Cleanup Site ID: 9611 Facility/Site ID: 53	734972	UST ID : 9800			Site Page		<u> Documents</u> <u>View Map</u>		
Cleanup Site Name: Safety Kleen Glossary									
Alternate Names: Safety Kleen, SAFETY KLEEN CORP, SAFETY KLEEN CORP LYNNWOOD, SAFETY KLEEN LYNNWOOD, SAFETY KLEEN SYSTEMS INC LYNNWOOD, SAFETY-KLEEN CORP									
LOCATION									
Address: 6303 212TH ST SW SUITE CCity: LYNNWOODZip Code: 98036County: Snohomish									
Latitude: 47.80668 Longitude: -122.31930 W	RIA: 8	Legislative Di	strict:	32 C	Congressio	onal Distri	ct: 2 TRS:	27N 4E 29	
DETAIL									
Status: No Further Action NFA Re	NFA Received? Yes			Is PSI site? No					
Statute: MTCA NFA Da	NFA Date: 6/12/2012			Current VCP? No Past VCP? No					
Site Rank: N/A NFA Re	NFA Reason: Initial Inve			ation Brownfield?					
Site Manager: Northwest Region Respon	ion Responsible Unit: Northwest			Active Institutional Control? No					
CLEANUP UNITS									
Cleanup Unit Name Unit Type	Unit S	itatus	Resp Unit	Unit	Unit Manager		Current Process		
SAFETY KLEEN Upland	Jpland No Further Action Requi			Northwest Region		n	Independent Action		
ACTIVE INSTITUTIONAL CONTROLS									
Instrument Type Restriction Media Restrict	Restrictions/Requirements			Date Recordi Numbe		•	Recording County Tax Parc		
There are no current Institutional Controls in effect for this site.									
AFFECTED MEDIA & CONTAMINANTS									
				MEDIA					
Contaminant	Soil	l Ground	water	Surfac	e Water	Sedimen	t Air	Bedrock	
Petroleum-Other	C								
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below									
SITE ACTIVITIES									
Activity				Status		Start Dat		nd Date/ pletion Date	
LUST - Notification				Completed			7/13/1994		
Site Discovery/Release Report Received				Completed			7.	/13/1994	
Initial Investigation / Federal Preliminary Assessment				Completed		5	5/30/2011		
Site Status Changed to NFA				Completed 6/12/2012					